

APPENDIX E
Photo-documentation Log

Field Team Leader's Site Observations
Camp Davis Site, Holly Ridge, North Carolina

Tuesday, November 13, 2007

Property: Camp Davis	Area: Remaining Lands	Time 2:12:01 PM	Point_ID: 1
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.567953951	
Sampler: Erich Stedman	MRSPP Note:	Longitude: -77.621558886	
Sample ID: CD-SS-02-02	Ambient collected 1.5 mi south of proposed sample location due to safety concerns regarding hunting.		
Barrier:	Topography: Flat		
Vegetation: Heavy Brush	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType: Sand	Subsurface Met: N/A		
SoilColor: Tan	MECMD: None		
			
SS-02 Sample location.	SS-02 Sample location.		

Property: Camp Davis	Area: Remaining Lands	Time 3:05:38 PM	Point_ID: 2
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.513027658	
Sampler: Steve Czekalski	MRSPP Note:	Longitude: -77.571057647	
Sample ID: CD-SS-02-01	Ambient sample.		
Barrier:	Topography: Flat		
Vegetation: Light Brush	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType: Loam	Subsurface Met: N/A		
SoilColor: Dark Brown	MECMD: None		
			
SS-01 Sample location.	SS-01 Sample location.		

Tuesday, November 13, 2007

Property: Camp Davis	Area: Coastal Gun Range	Time 3:34:55 PM	Point_ID: 3
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.423722396	
Sampler: Erich Stedman	MRSPP Note:	Longitude: -77.549992278	
Sample ID: CD-SS-02-07		Near coastal battery.	
Barrier:	Topography:		
Vegetation: Light Brush	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType: Loam	Subsurface Met: N/A		
SoilColor: Brown	MECMD: None		
			
SS-07 Sample location.	SS-07 Sample location.		
Property: Camp Davis	Area: Coastal Gun Range	Time 3:53:37 PM	Point_ID: 4
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.421801239	
Sampler: None	MRSPP Note:	Longitude: -77.550260895	
Sample ID: None			
Barrier:	Topography:		
Vegetation: Barren	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType: Sand	Subsurface Met: N/A		
SoilColor: Tan	MECMD: None		
			
North view of beach near Coastal AA Range.	South view of beach near Coastal AA Range.		

Tuesday, November 13, 2007

Property: Camp Davis	Area: Coastal Gun Range	Time 4:00:09 PM	Point_ID: 5
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.42375409	
Sampler: None	MRSPP Note:	Longitude: -77.550446115	
Sample ID: None			
Barrier:	Topography:		
Vegetation:	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType:	Subsurface Met: N/A		
SoilColor:	MECMD: None		
 Wood military storage building in Coastal AA Range MRS.			

Wednesday, November 14, 2007

Property: Camp Davis	Area: Range Complex No.1	Time 9:38:36 AM	Point_ID: 6
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.522248689	
Sampler: None	MRSPP Note: <input type="text"/>	Longitude: -77.606917787	
Sample ID: None	AA Range.		
Barrier: <input type="text"/>	Topography: <input type="text"/>	<input type="text"/>	
Vegetation: Heavy Brush	Surface Feature: <input type="text"/>	<input type="text"/>	
Drainage: None	Surface Debris: None	<input type="text"/>	
SoilType: Sand	Subsurface Met: N/A	<input type="text"/>	
SoilColor: Tan	MECMD: None	<input type="text"/>	
	<input type="text"/>	<input type="text"/>	<input type="text"/>
Pocosin swamp in Range Complex 1.			
Property: Camp Davis	Area: Range Complex No.1	Time 9:52:30 AM	Point_ID: 7
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.524640204	
Sampler: None	MRSPP Note: <input type="text"/>	Longitude: -77.608507227	
Sample ID: None	<input type="text"/>		
Barrier: <input type="text"/>	Topography: <input type="text"/>	<input type="text"/>	
Vegetation: <input type="text"/>	Surface Feature: <input type="text"/>	<input type="text"/>	
Drainage: None	Surface Debris: None	<input type="text"/>	
SoilType: <input type="text"/>	Subsurface Met: N/A	<input type="text"/>	
SoilColor: <input type="text"/>	MECMD: None	<input type="text"/>	
		<input type="text"/>	<input type="text"/>
Open field in Range Complex 1.		<input type="text"/>	

Wednesday, November 14, 2007

Property: Camp Davis	Area: Range Complex No.1	Time 9:56:13 AM	Point_ID: 8
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.525735738	
Sampler: None	MRSPP Note:	Longitude: -77.609621574	
Sample ID: None			
Barrier:	Topography: Flat	AA Range - MRS03.	
Vegetation:	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType:	Subsurface Met: N/A		
SoilColor:	MECMD: None		
			
Power line ROW passing through Range Complex 1.			
Property: Camp Davis	Area: Range Complex No.1	Time 10:40:22 AM	Point_ID: 9
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.519694799	
Sampler: Erich Stedman	MRSPP Note:	Longitude: -77.615121944	
Sample ID: CD-SS-02-09			
Barrier:	Topography: Flat	AA Range MRS03.	
Vegetation: Heavy Brush	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType: Sand	Subsurface Met: N/A		
SoilColor: Tan	MECMD: None		
			
SS-09 Sample location.			

Wednesday, November 14, 2007

Property: Camp Davis	Area: Range Complex No.1	Time 11:18:15 AM	Point_ID: 10
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.51604043	
Sampler: None	MRSPP Note: 	Longitude: -77.616117295	
Sample ID: None			
Barrier: 	Topography: 		
Vegetation: Heavy Brush	Surface Feature: 		
Drainage: None	Surface Debris: None		
SoilType: 	Subsurface Met: N/A		
SoilColor: 	MECMD: None		
			
Pocosin in Range Complex 1.	Pocosin in Range Complex 1.		

Property: Camp Davis	Area: Range Complex No.1	Time 11:50:39 AM	Point_ID: 11
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.516173255	
Sampler: None	MRSPP Note: 	Longitude: -77.6117835	
Sample ID: None			
Barrier: 	Topography: 		
Vegetation: 	Surface Feature: 		
Drainage: None	Surface Debris: None		
SoilType: 	Subsurface Met: N/A		
SoilColor: 	MECMD: None		
			
Berm near Track Target Range, Range Complex 1.			

Wednesday, November 14, 2007

Property: Camp Davis	Area: Range Complex No.1	Time 11:58:41 AM	Point_ID: 12
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.515642391	
Sampler: None	MRSPP Note:	Longitude: -77.609512162	
Sample ID: None			
Barrier:	Topography:		
Vegetation:	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType:	Subsurface Met: N/A		
SoilColor:	MECMD: None		
			
Berm 10 feet tall - part of Track Target.			
Property: Camp Davis	Area: Range Complex No.1	Time 12:29:38 PM	Point_ID: 13
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.519083113	
Sampler: None	MRSPP Note:	Longitude: -77.610917408	
Sample ID: None			
Barrier:	Topography:		
Vegetation:	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType:	Subsurface Met: N/A		
SoilColor:	MECMD: None		
			
South end of berm along Track Target.		South end of berm along Track Target.	

Wednesday, November 14, 2007

Property: Camp Davis	Area: Range Complex No.1	Time 12:43:57 PM	Point_ID: 14
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.51617283	
Sampler: None	MRSPP Note:	Longitude: -77.609951584	
Sample ID: CD-SS-02-05	Moved sample to bottom of track berm. Original sample located 800 feet to east.		
Barrier:	Topography:	SS-12 is field dup at 1152.	
Vegetation: Heavy Brush	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType: Loam	Subsurface Met: N/A		
SoilColor: Brown	MECMD: None		
			
SS-05 sample location at base of Track Target berm.	SS-05 at base of Track Target berm.		
Property: Camp Davis	Area: Range Complex No.1	Time 2:06:19 PM	Point_ID: 15
Team Leader: Erich Stedman	MRSPP Menu: None	Latitude: 34.520581529	
Sampler: None	MRSPP Note: Pitcher plant endangered	Longitude: -77.606312574	
Sample ID:			
Barrier:	Topography: Flat		
Vegetation: Grasses	Surface Feature: 4WD road		
Drainage: None	Surface Debris: None		
SoilType: Sand	Subsurface Met: N/A		
SoilColor: Tan	MECMD: None		
			
Pitcher plant in MRS03.			

Wednesday, November 14, 2007

Property: Camp Davis	Area: Remaining Lands	Time 2:24:39 PM	Point_ID: 16
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.507103373	
Sampler: None	MRSPP Note: <input type="text"/>	Longitude: -77.599901567	
Sample ID: <input type="text"/>	Found 2 .38 cal slugs at base of berm.		
Barrier: <input type="text"/>	Topography: <input type="text"/>	<input type="text"/>	
Vegetation: Thin Trees	Surface Feature: Berm	<input type="text"/>	
Drainage: None	Surface Debris: None	<input type="text"/>	
SoilType: Sand	Subsurface Met: N/A	<input type="text"/>	
SoilColor: <input type="text"/>	MECMD: Small Arms .30 cal	<input type="text"/>	
		<input type="text"/>	
Small arms berm south of Track Target Range		30 cal slugs.	

Property: Camp Davis	Area: Remaining Lands	Time 2:39:50 PM	Point_ID: 17
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.504878702	
Sampler: None	MRSPP Note: <input type="text"/>	Longitude: -77.594750889	
Sample ID: <input type="text"/>	<input type="text"/>		
Barrier: <input type="text"/>	Topography: <input type="text"/>	<input type="text"/>	
Vegetation: Thin Trees	Surface Feature: Berm	<input type="text"/>	
Drainage: None	Surface Debris: None	<input type="text"/>	
SoilType: Sand	Subsurface Met: N/A	<input type="text"/>	
SoilColor: <input type="text"/>	MECMD: None	<input type="text"/>	
		<input type="text"/>	
2nd small arms berm south of Track Target Range.		<input type="text"/>	

Wednesday, November 14, 2007

Property: Camp Davis	Area: Remaining Land	Time 2:58:39 PM	Point_ID: 18
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.490863902	
Sampler: Erich Stedman	MRSPP Note:	Longitude: -77.586568261	
Sample ID: CD-SS-02-03		Ambient sample.	
Barrier:	Topography:		
Vegetation: Light Brush	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType: Loam	Subsurface Met: N/A		
SoilColor: Brown	MECMD: None		
			
SS-03 sample location.			

Property: Camp Davis	Area: Range Complex No.1	Time 3:43:36 PM	Point_ID: 19
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.539024316	
Sampler: Erich Stedman	MRSPP Note:	Longitude: -77.600972294	
Sample ID: CD-SS-02-06		Grenade court.	
Barrier:	Topography:		
Vegetation: Heavy Brush	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType: Sand	Subsurface Met: N/A		
SoilColor: Dark Brown	MECMD: None		
			
SS-06 sample location near Grenade Court, part of Range Complex 1.			

Wednesday, November 14, 2007

Property: Camp Davis	Area: Range Complex No.1	Time 4:07:32 PM	Point_ID: 20
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.536601128	
Sampler: Erich Stedman	MRSPP Note:	Longitude: -77.602337451	
Sample ID: CD-SS-02-04	Moved Sample SS-04 to this location.		
Barrier:	Topography: Flat		
Vegetation: Heavy Brush	Surface Feature:		
Drainage: None	Surface Debris: Medium Density		
SoilType: Sand	Subsurface Met: N/A		
SoilColor:	MECMD: Small Arms .30 cal		
			
1943 .50 cal casing (expended).	30 cal round full (not expended).		

Thursday, November 15, 2007

Property: Camp Davis	Area: Range Complex No.1	Time 10:03:46 AM	Point_ID: 21
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.534838261	
Sampler: None	MRSPP Note:	Longitude: -77.607321405	
Sample ID: None			
Barrier:	Topography:		
Vegetation:	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType:	Subsurface Met: N/A		
SoilColor:	MECMD: None		
			
Logging along centerline of AA Range in Range Complex 1.			
Property: Camp Davis	Area: Range Complex No.1	Time 10:14:33 AM	Point_ID: 22
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.536708387	
Sampler: None	MRSPP Note:	Longitude: -77.609919192	
Sample ID: None		Deforested area.	
Barrier:	Topography:		
Vegetation: Thin Trees	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType: Sand	Subsurface Met: N/A		
SoilColor: Black	MECMD: None		
			
Centerline of AA Range in Range Complex 1.			

Thursday, November 15, 2007

Property: Camp Davis	Area: Range Complex No.1	Time 11:00:58 AM	Point_ID: 23
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.528699812	
Sampler: None	MRSPP Note: 	Longitude: -77.602749635	
Sample ID: None			
Barrier: 	Topography: 		
Vegetation: 	Surface Feature: 		
Drainage: None	Surface Debris: None		
SoilType: 	Subsurface Met: N/A		
SoilColor: 	MECMD: 37mm Shell		
			
37mm TPT found at hunters cabin in Range Complex 1.	Base of observation tower in Range Complex 1.		
Property: Camp Davis	Area: Range Complex No.1	Time 11:45:20 AM	Point_ID: 24
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.474652713	
Sampler: None	MRSPP Note: 	Longitude: -77.587051828	
Sample ID: None			
Barrier: 	Topography: 		
Vegetation: 	Surface Feature: 		
Drainage: None	Surface Debris: None		
SoilType: 	Subsurface Met: N/A		
SoilColor: 	MECMD: None		
			
Very heavy brush downrange of Rifle Range.	Very heavy brush downrange of Rifle Range.		

Thursday, November 15, 2007

Property:	Camp Davis	Area:	Rifle/Pistol Range	Time	1:53:26 PM	Point_ID:	25
Team Leader	Steve Czekalski	MRSPP Menu:	None	Latitude:	34.473021438		
Sampler:	None	MRSPP Note:		Longitude:	-77.583424671		
Sample ID:	None						
Barrier:		Topography:					
Vegetation:		Surface Feature:					
Drainage:	None	Surface Debris:	None				
SoilType:		Subsurface Met:	N/A				
SoilColor:		MECMD:	None				
							
Rear of backstop to Rifle/Pistol Range.							

Property:	Camp Davis	Area:	Rifle/Pistol Range	Time	2:00:13 PM	Point_ID:	26
Team Leader	Steve Czekalski	MRSPP Menu:	None	Latitude:	34.472447775		
Sampler:	None	MRSPP Note:		Longitude:	-77.583208794		
Sample ID:	CD-SS-02-11						
Barrier:		Topography:					
Vegetation:	Light Brush	Surface Feature:	Target				
Drainage:	None	Surface Debris:	None				
SoilType:	Sand	Subsurface Met:	N/A				
SoilColor:		MECMD:	Small Arms .30 cal				
							
Small arms slug found at base of soil berm in front of backstop.							
							
SS-11 Sample location.							

Thursday, November 15, 2007

Property:	Camp Davis	Area:	Rifle/Pistol Range	Time	2:05:03 PM	Point_ID:	27
Team Leader	Steve Czekalski	MRSPP Menu:	None	Latitude:	34.471914101		
Sampler:	None	MRSPP Note:		Longitude:	-77.583172963		
Sample ID:	None						
Barrier:		Topography:					
Vegetation:		Surface Feature:					
Drainage:	None	Surface Debris:	None				
SoilType:		Subsurface Met:	N/A				
SoilColor:		MECMD:	None				
							
Soil removed from front of firing backstop.		Concrete backstop Rifle/Pistol Range.					

Property:	Camp Davis	Area:	Rifle/Pistol Range	Time	2:09:56 PM	Point_ID:	28
Team Leader	Steve Czekalski	MRSPP Menu:	None	Latitude:	34.473009263		
Sampler:	None	MRSPP Note:		Longitude:	-77.58311708		
Sample ID:	None						
Barrier:		Topography:					
Vegetation:		Surface Feature:					
Drainage:	None	Surface Debris:	None				
SoilType:		Subsurface Met:	N/A				
SoilColor:		MECMD:	None				
							
North section of South back stop.							

Thursday, November 15, 2007

Property: Camp Davis	Area: Rifle/Pistol Range	Time 2:12:19 PM	Point_ID: 29
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.47354196	
Sampler: None	MRSPP Note:	Longitude: -77.583368103	
Sample ID: None			
Barrier:	Topography:		
Vegetation:	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType:	Subsurface Met: N/A		
SoilColor:	MECMD: None		
			
North wall soil removed.			

Property: Camp Davis	Area: Rifle/Pistol Range	Time 2:33:42 PM	Point_ID: 30
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.478039129	
Sampler: None	MRSPP Note:	Longitude: -77.584122821	
Sample ID: None			
Barrier:	Topography:		
Vegetation:	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType:	Subsurface Met: N/A		
SoilColor:	MECMD: None		
			
Second backstop from south (2 of 4 backstops).			

Thursday, November 15, 2007

Property: Camp Davis	Area: Rifle/Pistol Range	Time 2:58:44 PM	Point_ID: 31
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.464905762	
Sampler: None	MRSPP Note:	Longitude: -77.615365625	
Sample ID: None			
Barrier:	Topography:		
Vegetation:	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType:	Subsurface Met: N/A		
SoilColor:	MECMD: None		
			
5 residences in Rifle/Pistol Range MRS.			

Property: Camp Davis	Area: Rifle/Pistol Range	Time 3:06:26 PM	Point_ID: 32
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.469711259	
Sampler: None	MRSPP Note:	Longitude: -77.607473381	
Sample ID: None			
Barrier:	Topography:		
Vegetation:	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType:	Subsurface Met: N/A		
SoilColor:	MECMD: None		
			
10 residential units in Rifle/Pistol Range MRS.			

Thursday, November 15, 2007

Property: Camp Davis	Area: Rifle/Pistol Range	Time 3:14:12 PM	Point_ID: 33
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.466991196	
Sampler: Erich Stedman	MRSPP Note:	Longitude: -77.609245235	
Sample ID: CD-SS-02-10		Downrange in Rifle/Pistol Range.	
Barrier:	Topography:		
Vegetation:	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType:	Subsurface Met: N/A		
SoilColor:	MECMD: None		
			
SS-10 Sample location.	SS-10 Sample location.		

Property: Camp Davis	Area: Range Complex No.1	Time 4:38:54 PM	Point_ID: 34
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.546948195	
Sampler: Erich Stedman	MRSPP Note:	Longitude: -77.680252201	
Sample ID: CD-SS-02-08		FD SS-13 time is 1520.	
Barrier:	Topography:		
Vegetation: Light Brush	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType: Sand	Subsurface Met: N/A		
SoilColor: Black	MECMD: None		
			
SS-08 Sample location.	Deforested area in Range Complex 1.		
			
		Pocosin in Range Complex 1.	

Friday, November 16, 2007

Property: Camp Davis	Area: Range Complex No.1	Time 8:30:42 AM	Point_ID: 35
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.525018728	
Sampler: None	MRSPP Note:	Longitude: -77.714728506	
Sample ID: None			
Barrier:	Topography:		
Vegetation:	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType:	Subsurface Met: N/A		
SoilColor:	MECMD: None		
			
Pocosin swamp along south central AA Range			

Property: Camp Davis	Area: Range Complex No.1	Time 8:41:45 AM	Point_ID: 36
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.521859426	
Sampler: None	MRSPP Note:	Longitude: -77.702180982	
Sample ID: None		QR done along road as pocosin is impenetrable/swampy.	
Barrier:	Topography:		
Vegetation: Heavy Brush	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType:	Subsurface Met: N/A		
SoilColor:	MECMD: None		
			
QR Track along SE AA Range,			

Friday, November 16, 2007

Property: Camp Davis	Area: Range Complex No.1	Time 8:55:55 AM	Point_ID: 37
Team Leader: <input type="text"/>	MRSPP Menu: None	Latitude: 34.519492024	
Sampler: None	MRSPP Note: <input type="text"/>	Longitude: -77.692733837	
Sample ID: <input type="text"/>			
Barrier: <input type="text"/>	Topography: <input type="text"/>		
Vegetation: Heavy Brush	Surface Feature: <input type="text"/>		
Drainage: None	Surface Debris: None		
SoilType: <input type="text"/>	Subsurface Met: N/A		
SoilColor: <input type="text"/>	MECMD: None		
			
Juniper Rd passing through Track Target and AA Ranges.			
Property: Camp Davis	Area: Range Complex No.1	Time 9:06:36 AM	Point_ID: 38
Team Leader: <input type="text"/>	MRSPP Menu: None	Latitude: 34.520103908	
Sampler: None	MRSPP Note: <input type="text"/>	Longitude: -77.687660253	
Sample ID: <input type="text"/>			
Barrier: <input type="text"/>	Topography: <input type="text"/>		
Vegetation: Heavy Brush	Surface Feature: <input type="text"/>		
Drainage: None	Surface Debris: None		
SoilType: <input type="text"/>	Subsurface Met: N/A		
SoilColor: <input type="text"/>	MECMD: None		
			
Pocosin along QR route in Range Complex 1.			

Friday, November 16, 2007

Property: Camp Davis	Area: Range Complex No.1	Time 9:39:48 AM	Point_ID: 39
Team Leader: Steve Czekalski	MRSPP Menu: None	Latitude: 34.529734796	
Sampler: None	MRSPP Note:	Longitude: -77.676464249	
Sample ID: None			
Barrier:	Topography:		
Vegetation: Heavy Brush	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType:	Subsurface Met: N/A		
SoilColor:	MECMD: None		
			
Pocosin in MRS03.	Road passing through AA Range.		

Property: Camp Davis	Area: Range Complex No.1	Time 9:53:59 AM	Point_ID: 40
Team Leader:	MRSPP Menu: None	Latitude: 34.53783991	
Sampler: None	MRSPP Note:	Longitude: -77.678376605	
Sample ID: None			
Barrier:	Topography:		
Vegetation: Heavy Brush	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType:	Subsurface Met: N/A		
SoilColor:	MECMD: None		
			
Typical thickness of pocosin at Camp Davis.			

Friday, November 16, 2007

Property: Camp Davis	Area: Range Complex No.1	Time 10:18:16 AM	Point_ID: 41
Team Leader Steve Czekalski	MRSPP Menu: None	Latitude: 34.549147212	
Sampler: None	MRSPP Note: <input type="text"/>	Longitude: -77.680990965	
Sample ID: <input type="text"/>			
Barrier: <input type="text"/>	Topography: <input type="text"/>		
Vegetation: Mixed Trees + Brush	Surface Feature: <input type="text"/>		
Drainage: None	Surface Debris: None		
SoilType: <input type="text"/>	Subsurface Met: N/A		
SoilColor: <input type="text"/>	MECMD: None		
			
Grassland in south AA Range.	Young pocosin in AA Range.		

Property: Camp Davis	Area: Range Complex No.1	Time 10:22:24 AM	Point_ID: 42
Team Leader <input type="text"/>	MRSPP Menu: None	Latitude: 34.549213651	
Sampler: None	MRSPP Note: <input type="text"/>	Longitude: -77.680375351	
Sample ID: <input type="text"/>			
Barrier: <input type="text"/>	Topography: <input type="text"/>		
Vegetation: <input type="text"/>	Surface Feature: <input type="text"/>		
Drainage: None	Surface Debris: None		
SoilType: <input type="text"/>	Subsurface Met: N/A		
SoilColor: <input type="text"/>	MECMD: None		
			
Pitcher plant in MRS03.	Pitcher plant in MRS03.		
			
Pitcher plant in MRS03.			

Friday, November 16, 2007

Property: Camp Davis	Area: Range Complex No.1	Time 11:48:42 AM	Point_ID: 43
Team Leader	MRSPP Menu: None	Latitude: 34.543427028	
Sampler: None	MRSPP Note:	Longitude: -77.582050698	
Sample ID: None		8 homes north of MRS03	
Barrier:	Topography:		
Vegetation:	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType:	Subsurface Met: N/A		
SoilColor:	MECMD: None		
No Photo			

Property: Camp Davis	Area: Range Complex No.1	Time 11:55:05 AM	Point_ID: 44
Team Leader	MRSPP Menu: None	Latitude: 34.524542958	
Sampler: None	MRSPP Note:	Longitude: -77.585523335	
Sample ID: None		5 Houses north of MRS03	
Barrier:	Topography:		
Vegetation:	Surface Feature:		
Drainage: None	Surface Debris: None		
SoilType:	Subsurface Met: N/A		
SoilColor:	MECMD: None		
No Photo			